




PLUG

JACK

	PLUG
	最小值
A	6.35
B	4.53
C	2.54
D	0.00
E	1.91
F	0.00
G	0.90
J	1.24

	JACK
	最小值
A	5.28
B	4.60
C	1.88
D	0.00
E	0.38
F	2.92
G	0.00
H	4.32
J	1.24
K	5.54

000000|000000|000000|2MM000|SMA000|000|000-00000000000000
000000SMA-KWHD-14.7

sma 50 : , , , , ,
 :

SMA□□□□